

CERTIFICATE OF COMPLIANCE

Certificate Number 20170815 – EX27533
Report Reference EX27533 – 20170606
Issue Date 2017-AUGUST-15

Issued to: ARITA VALVE (HOUSTON) INC
4607 DECKER DRIVE
KATY, TX 77494 USA

**This is to certify that
representative samples of**

Butterfly Valves
Butterfly valve: AFF-BF-25G-300, AFF-BF-25W-300,
AFF-BF-25L-300, AFF-BF-26FG-175, AFF-BF-26FG-300,
AFF-BF-26G-175, AFF-BF-26G-300, AFF-BF-27FG-175,
AFF-BF-27FG-300, AFF-BF-27G-175, AFF-BF-27G-300,
AFF-BF-28G-300, AFF-BF-28W-300

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1091, "Butterfly Valves for Fire-Protection Service."
Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20170815 – EX27532
Report Reference EX27532 – 20170605
Issue Date 2017-AUGUST-15

Issued to: ARITA VALVE (HOUSTON) INC
4607 DECKER DRIVE
KATY, TX 77494 USA

**This is to certify that
representative samples of** Gate Valves
(See Addendum)

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 262, "Gate Valves for Fire-Protection Service."
Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE


Certificate Number 20170815 – EX27532
Report Reference EX27532 – 20170605
Issue Date 2017-AUGUST-15

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Addendum –

Resilient seated gate valves:

AFF-RGA-33FF-300, AFF-RGA-33GG-300, AFF-RGA-33FG-300, AFF-RGA-33FM-300, AFF-RGA-33MJ-300, AFF-RGA-33FF-250, AFF-RGA-33GG-250, AFF-RGA-33FG-250, AFF-RGA-33FM-250, AFF-RGA-33MJ-250, AFF-RGA-33FF-200, AFF-RGA-33GG-200, AFF-RGA-33FG-200, AFF-RGA-33FM-200, AFF-RGA-33MJ-200, AFF-NGA-32FF-300, AFF-NGA-32GG-300, AFF-NGA-32FG-300, AFF-NGA-32FM-300, AFF-NGA-32MJ-300, AFF-NGA-32FF-250, AFF-NGA-32GG-250, AFF-NGA-32FG-250, AFF-NGA-32FM-250, AFF-NGA-32MJ-250, AFF-NGA-32FF-200, AFF-NGA-32GG-200, AFF-NGA-32FG-200, AFF-NGA-32FM-200, AFF-NGA-32MJ-200, AFF-RGA-33FF, AFF-NGA-32FF



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number EX28725
Report Reference EX28725-20220302
Issue Date 2022-MARCH-02

Issued to: Arita Valve (Houston) Inc
7075 Fm 1960 Rd W Ste 16 Houston TX US US 77069

This certificate confirms that representative samples of CHECK VALVES
See addendum page for Models/Product


Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 312 - Check Valves for Fire-Protection Service
Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number EX28725
Report Reference EX28725-20220302
Issue Date 2022-MARCH-02

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

50FF-300
50GG-365
50GGP-365
50W
55FF
56GG-350
56FF-350
56FG-350
56GF-350
57FF-300



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

